Job No. L-D7262 Date- 01/03/2023

		Date- 01/03/2023	
S.No.	DEFECTS FOUND	RECTIFICATION	REMARK
	MC contactor addon block to be replace	To be replace	
	Car shoe play to be adjust	To be adjust	
3	Some floor shaft light not working	To be replace	Customer scope
4	Latch to be change, 21,19,18,15,11,G,UB floor	To be replace	
5	Door spring to be change 23,22,19,14,8th floor	To be replace	
6	Car top and pit to be clean	To be done	
7	V roller to be change at 19,18,13,5,4th floor	To be replace	
8	Flat stopper to be fix at 21, 16, 13, 11 floor	To be replace	
9	OSG weight to be straight	To be done	
10	D locking lever to be change at 17th floor	To be replace	
11	Display glass to be change at 12,8,4,2 floor	To be replace	
12	Display to be change at 18th floor	To be replace	
	Emergency light- OK		
	ARD- OK		
	Alarm- OK		